

## iPod Nano 6 Display Breakout - Issues

#	Tracker	Status	Priority	Subject	Assignee	Updated
471	Bug	Feedback	Normal	3.3VEN signal is active low... make it active high	Andrew Kohlsmith	03/18/2015 09:24 PM
602	Bug	New	Normal	boost converter won't boost high enough	Andrew Kohlsmith	03/18/2015 08:21 PM
600	Bug	Feedback	Normal	Internal short between LED+ and RST#	Andrew Kohlsmith	03/18/2015 05:42 PM
469	Bug	Feedback	Normal	RST#, BL lines should have pulldown as appropriate	Andrew Kohlsmith	03/01/2014 10:07 PM
601	Bug	Feedback	Normal	TLV61220 footprint wrong	Andrew Kohlsmith	03/18/2015 08:47 PM